

US EPA ARCHIVE DOCUMENT

# Situation Photo Log

Tuesday, March 6, 2012

Kalamazoo River / Enbridge Spill

US EPA ARCHIVE DOCUMENT

Prepared by:

Matthew Haak  
START-USEPA  
Situation Unit Leader



1. Turbidity Control Structure observed being demobilized.



2. Turbidity Control Structure observed being demobilized.





3. Turbidity Control Structure observed being demobilized.



4. Turbidity Control Structure observed being demobilized.





5. Talmadge Creek: restoration work south of A Drive.



6. Talmadge Creek: restoration work south of A Drive.





7. Talmadge Creek: restoration work near MP1.9.



8. Talmadge Creek demobilizing of pumps near MP1.9.





9. Talmadge Creek demobilizing of GAC system from near MP1.85.



10. Confluence sheet piling removed from area prior to excavation.





11. Confluence sheet piling removed from area prior to excavation.



12. Confluence SWAT observed adjusting boom prior to sheet pile installation.





13. Confluence SWAT observed adjusting boom prior to sheet pile installation



14. Confluence observed sheet piling installation at diversion structure discharge.





**15. Confluence observed sheet piling installation at diversion structure discharge.**



**16. Confluence observed crews removing super sacks from area to be excavated.**





17. Confluence observed central sheet piling at diversion structure discharge.



18. Talmadge Creek observed water quality monitoring.





19. Confluence: turbidity observed.



20. Confluence: turbidity observed.





21. Confluence: observed removal of the diversion structure.



22. Confluence: observed removal of the diversion structure.





23. Confluence: observed removal of the diversion structure culvert.



24. Confluence: observed removal of the diversion structure.





25. Confluence: observed removal of the diversion structure.



26. Confluence: sheen observed during the removal of the diversion structure.





27. Confluence: sheen observed during the removal of the diversion structure.




28. Confluence: observed dewatering at diversion structure discharge.





29. Temperature effects study.



30. Temperature effects study.



31. Frac-City vac-truck roll off emptied in to Cell A.



32. Vac-Truck offloading GAC contents.





33. Vac-Truck offloading GAC contents.



34. Frac-City observed frac-tank being decontaminated.